

## GRADE LEVELS

### A2

Must be able to speak, read and write, as well as perform basic shop math. Ability to use measuring tools. Must be able to operate power tools. Must be able to make simple set-ups and operate multiple machines in assigned work area. Ability to perform other job related duties and responsibilities as may be assigned. Must be able to work with shop floor personnel. Must have a positive attitude. Must be dependable. Must have machinery knowledge for assigned area.

### A1

Must be able to speak, read and write, as well as perform basic shop math. Ability to use measuring tools. Must be able to read blueprints. Must be able to operate power tools. Must be able to make most set-ups and operate multiple machines in assigned work area. Ability to perform other job related duties and responsibilities as may be assigned. Must be able to work with shop floor personnel. Must have positive a attitude. Must be dependable. Must have machinery knowledge for assigned area. Requires minimal assistance from AA or CC.

### A

Must be able to speak, read and write, as well as perform basic shop math. Ability to use measuring tools. Must be able to read blueprints. Must be able to operate power tools. Must be able to make routine set-ups and operate multiple machines in assigned work area. Ability to perform other job related duties and responsibilities as may be assigned. Must be able to work with shop floor personnel. Must have a positive attitude. Must be dependable. Must have machinery knowledge for assigned area. Requires minimal assistance from AA or CC.

### AA

Must be able to speak, read and write, as well as perform basic shop math. Ability to use measuring tools. Must be able to read blueprints. Must be able to operate power tools. Must be able to make multiple set-ups and operate multiple machines in assigned work area. Ability to perform other job related duties and responsibilities as may be assigned. Must be able to work with shop floor personnel. Must have a positive attitude. Must have exemplary dependability. Must have machinery knowledge for assigned area. Requires minimal assistance from CC.

### CC

Leadership ability through communication. Knowledge of the standard practices, methods, materials and tools of manufacturing departments. Knowledge of occupational hazards and safety precautions of manufacturing departments. Knowledge of mechanical systems and processes. Must be able to speak, read and write, as well as perform basic shop math. Ability to use measuring tools. Must be able to read blueprints. Must be able to operate power tools. Must be able to make multiple set-ups and operate multiple machines in assigned work area. Ability to perform other job related duties and responsibilities as may be assigned. Must be able to work with shop floor personnel. Must have positive a attitude. Must have exemplary dependability. Must have machinery knowledge for assigned area. Requires minimal assistance from Supervisor.