



April 28, 2008

Letter Report No. 3149704COQ-005
Project No. 3149704

Mr. Shaun Ray
Metal-Fab, Inc.
P.O. Box 1138
Wichita, KS 67201

Ph: 316-943-4031
Fax: 316-943-2717
email: shaunr@mtlfab.com


Subject: Use of Metal-Fab Sure-Seal DV Direct Vent Venting Systems on Kingsman Industries Ltd. Direct Vented Gas Fireplaces


Dear Mr. Ray,

Intertek has evaluated the Metal-Fab Sure-Seal Direct Vent Venting Systems for construction, leakage, and for combustion on several direct vent appliances for compliance with UL Subject 2112-2000 and applicable sections of ANSI Z21.88-2006 • CSA 2.33-2006 and ANSI Z21.50-2003 • CSA 2.33-2003. As a result of these evaluations, Intertek has deemed the Metal-Fab Sure-Seal Direct Vent Venting System is acceptable for use on all Kingsman Industries Ltd. direct vent appliances listed with the Warnock Hersey mark. All manufacturers with an appliance listed with a Warnock Hersey mark who wish to accept the use of the Metal-Fab Sure-Seal Direct venting system on their product, must submit either a revised instruction manual or an appendix to an existing instruction manual indicating the use of the Metal-Fab Sure-Seal Direct venting to Intertek for review.

Completed by: Kevin Stanichuk
Senior Project Leader
Gas and Hearth Products

Reviewed by: Ian Chang, P.Eng.
Manager
Hearth and Plumbing Products

Signature: 
Date: April 25/08

Signature: 
Date: April 25, 2008



An Independent Organization Testing for Safety and Performance

Page 1 of 1

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report by itself does not imply that the material, product or service is or has ever been under an Intertek certification program.